

QUESTIONS & ANSWERS

1. QUESTION: For the Gavins Point Replacement Operator Console. Is steel an acceptable material for the frame of the consoles? Or, are the consoles made up of just wood panels?

ANSWER: A metal frame is an acceptable material for the frame only, the panels made of wood

2. QUESTION: What the U.S. Army Corps of Engineers has estimated the size or magnitude of this project (in dollars) to be?

ANSWER: Magnitude IAW FAR 36.204 would be (b) between \$25,000 and \$100,000.